

Wreckage of Kennedy plane found

New details from final radar traces of JFK Jr.'s plane show the final descent may have exceeded 5,000ft per minute, hitting the water at a steep angle and breaking apart on impact. Aviation experts say the speed indicates classic 'stall-spin syndrome' – an aircraft spiralling out of control

