

Shuttle's damaged heat shield

Astronauts from the U.S. space shuttle Endeavour are examining damage to its heat shield sustained during take-off from Cape Canaveral.

A close-up laser inspection has revealed that a 7cm-long gouge penetrates all the way through the thermal shielding on the shuttle's belly

