



Throttle problem suspected in jet crash

Indonesian investigators say that a malfunction of the auto-throttle system, which controls the thrust of a plane's engines, may have led to the crash of a Sriwijaya Air jet on Jan 9 that killed all 62 people on board



FINAL MOMENTS OF FLIGHT SJ182



All times local (GMT+7)

Picture: Getty Images

Sources: Indonesia's National Transportation Safety Committee (KNKT), FlightRadar24 © GRAPHIC NEWS