


FAA urges more Boeing 737 checks

The U.S. Federal Aviation Administration is recommending that airlines inspect Boeing 737-900ER aircraft, which use the same door plug design as the grounded 737 MAX 9

MAJOR OPERATORS OF BOEING 737-900ER



Total
737-900ER
delivered
worldwide
505



Boeing 737 MAX 9: Jets containing door plug grounded by FAA after Jan 5 mid-air blowout on Alaska Airlines plane left gaping hole in fuselage

Total
737 MAX 9
grounded
171



Note: Not all models of planes have door plugs, depending on seating configuration